ame of Inspector: Frank Donroe	Signature: A Don	>	
ate of Inspection: 2-9-18	Time inspection started: 1pm		
) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDE	NTIFIED PROBLEMS IMMEDIATELY TO THE V	VEP COORDINATOR.	
Key:	AREAS SUBJECT TO INSPECTION		Additional Comments
Satisfactory - S, Not Applicable - NA, See Comment Section - C	Southside of Bldg.	Northside of Bldg.	
rocess Wastewater Management			
re there any hoses or signs of washing of vehicles or equipment (e.g. pats) outside?	S	s	
terview one employee to assiss compliance with this policy?			Name: Wayne xxxxxx
there a posting inside the building notifying workers of proper process aste water management?	s	s	
e there posting outside the building notifying workers of proper ocess wastewater management	S	S	

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204.5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH AT (718) 641.7400 OR AQUEDUCT MAIN SECURITY AT (718)659.3511