Name of Inspector: Frank Donroe	Signature: 2 Donne		
Date of Inspection: 6-8-18	Time Inspection Started: 11am		
1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL II	DENTIFIED PROBLEMS IMMEDIATELY TO THE WI	EP COORDINATOR.	
Key: Satisfactory - S, Not Applicable - NA, See Comment Section - C	AREAS SUBJECT TO INSPECTION		Additional Comments
	Southside of Bldg.	Northside of Bldg.	No horses on site
Process Wastewater Management	 		
Are there any hoses or signs of washing of vehicles or equipment (e.g. floats) outside?	S	S	
Interview one employee to assiss compliance with this policy?			Name: Paul xxxxx
Is there a posting inside the building notifying workers of proper proces waste water management?	s s	s	
Are there posting outside the building notifying workers of proper process wastewater management	S	s	

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204.5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH AT (718) 641.7400 OR AQUEDUCT MAIN SECURITY AT (718)659.3511