

Name of Inspector: Frank Donroe  
 Signature:   
 Date of Inspection: 3-15-19  
 Time Inspection started: 1:2pm

**1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDENTIFIED PROBLEMS IMMEDIATELY TO THE WEP COORDINATOR.**

Key:		AREAS SUBJECT TO INSPECTION		Additional Comments
Satisfactory - S, Not Applicable - NA, See Comment Section - C	Southside of Bldg.	Northside of Bldg.		
<b>Process Wastewater Management</b>				
Are there any hoses or signs of washing of vehicles or equipment (e.g. floats) outside?	S		S	
Interview one employee to assess compliance with this policy?				Name: Jason xxxx
Is there a posting inside the building notifying workers of proper process waste water management?	S		S	
Are there posting outside the building notifying workers of proper process wastewater management?	S		S	

**Other Issues: Pump #2 is being repaired.**

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204.5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH AT (718) 641.7400 OR AQUEDUCT MAIN SECURITY AT (718)659.3511